TO:

File

FROM:

Frank Jensen, Soils Reclamation Specialist Frank Jensen

RE:

Southwest Portland Cement Co., Nielson Sandstone Quarry,

ACT/023/012 (Formerly DOE/023/025)

On May 14, 1987 Terry Kerby of the company and I reviewed the subject case, as they are completing an MR-1 because they plan to expand the quarry.

I gave the company a suggested seed mixture, fertilization rate, and other information for their MR-1.

We also ran a vegetation transect to determine ground The result of the transect was:

Ground Cover

Vegetation	Percentage
Bluebunch wheatgrass Bluegrass (Poe spp.) Big sagebrush	5 1 6
Total ground cover	12
Litter Rock and Pavement Bare Ground	7 22 59
	100

*Note: There is also an overstory of five to ten percent Utah Juniper which was not counted as ground cover.

With a vegetative ground cover of 12 percent reclamation efforts will need to reestablish eight percent ground cover (70 percent of original). Following are photographs of this site:

Page 2
Memorandum - ACT/023/012
Nielson Sandstone Quarry
May 27, 1987



Photo #1 - Nielson Sandstone Quarry - May 21, 1987. This quarry #s southfacing and will be somewhat hard to revegetate unless a good layer (1-2 feet) of topsoil is put on the disturbed areas. If that much topsoil is put on and they are seeded properly, it will be possible to reestablish the required eight percent ground cover.

Note: The red colored vegetation is cheatgrass. It was not counted in the transect.

Page 3 Memorandum - ACT/023/012 Nielson Sandstone Quarry May 27, 1987



Photo #2 - This area, near the quarry, was reseeded by the Bureau of Land Management following a fire. It is a good seeding of crested wheatgrass and Russian wildrye. With this area so close, there is no need for a seeding study plot. (Terry Kerby in photograph).

clj
cc: Southwest Portland Cement Company
1117R/79